

## SPP HPE Custom Image vibsdepot mapping for Pre-Gen9

This document does not apply to HPE Superdome servers. For information on HPE Superdome, see the following links:

- [HPE Integrity Superdome X](#)
- [HPE Superdome Flex](#)

### HPE Custom Image to SPP Mapping

Use the following links to view the table that maps the HPE Custom Images for the OS release to the vibsdepot directory and the matching SPP release for Pre-Gen9 servers. The vibsdepot directory contains all the drivers and software added to the referenced HPE Custom Image, or the drivers and software for a hot-fix for the referenced HPE Custom Image as described in the footnotes. The SPP contains the drivers included in the referenced HPE Custom Image and the matching FW components. Starting with the 2018.03.0 SPP, the HPE value-add software included in the referenced HPE Custom Image is also included in the SPP.

Use the SPP link in the table to view detailed information on where to obtain the appropriate firmware, drivers and software for the supported OS releases and server generations for the SPP release. SPP documentation and downloads for all the SPP releases can be found at <http://www.hpe.com/servers/spp/download>. The SPP Component Release Notes contain a detailed list of all the firmware and driver components included in the SPP.

The tables map the HPE Custom Image to the SPP that matches the content of that HPE Custom Image. For information on how to update to a newer SPPs, see section [Updating to Newer SPPs](#) below.

[VMware vSphere 6.7 U2](#)

[VMware vSphere 6.7 U1](#)

[VMware vSphere 6.7](#)

[VMware vSphere 6.5 U2](#)

[VMware vSphere 6.5 U1](#)

[VMware vSphere 6.5](#)

[VMware vSphere 6.0 U3](#)

[VMware vSphere 6.0 U2](#)

[VMware vSphere 6.0 U1](#)

[VMware vSphere 5.5 U3](#)

## SPP and HPE Software and Driver Mapping

Use the following links to view detailed information on where to obtain the appropriate firmware, drivers and software for the supported OS releases and server generations for the SPP release. Starting with the 2018.03.0 SPP, the HPE value-add software included in the referenced HPE Custom Image is also included in the SPP.

The tables map the HPE Custom Image to the SPP that matches the content of that HPE Custom Image. For information on how to update to a newer SPPs, see section [Updating to Newer SPPs](#) below.

[2019.03.1](#)

[2019.03.0](#)

[2018.11.0](#)

[2018.09.0](#)

[2018.06.0](#)

[2018.03.0](#)

[2017.10.1](#)

[2017.07.2](#)

[Gen8.1 Post Production SPP](#)

[G7.1 Post Production SPP](#)

[2017.04.0](#)

[2016.10.0](#)

[2016.04.0](#)

[2015.10.0](#)

## Updating to newer SPPs

The table in the Important Notes section in the VMware Software Recipe documents available on <http://vibsdepot.hpe.com> list all previously released HPE Custom Images that can be updated using the referenced SPP and vibsdepot directories. For example, the entry below from the June 2017 VMware Software Recipe for the Service Pack for ProLiant (SPP) Version 2017.04.0 indicates that the HPE Custom Image for VMware vSphere 6.0 Update 2 (09 December 2016) can use the feb2017 vibsdepot directory to update the drivers and software to match the FW in the 2017.04.0 SPP.

OS Version	HPE Custom Image	HPE Custom Image Identifier	Driver Updates	Software Updates
vSphere 6.0 Update 2	HPE Custom Image for VMware vSphere 6.0 Update 2 (09 December 2016)	hpe-build-600.9.6.5.7-2494585	<p><b>Driver Updates are required</b></p> <p>Image does not contain driver versions specified in this Recipe</p> <p>Required drivers are available from: VUM online updates at: <a href="http://vibsdepot.hpe.com/hpe/preGen9/feb2017/index-driv.xml">http://vibsdepot.hpe.com/hpe/preGen9/feb2017/index-driv.xml</a></p> <p>Offline bundles updated at: <a href="http://vibsdepot.hpe.com/hpe/preGen9/feb2017/esxi-600-devicedrivers">http://vibsdepot.hpe.com/hpe/preGen9/feb2017/esxi-600-devicedrivers</a></p> <p>(SPP) 2017.04.0 at: <a href="http://www.hpe.com/servers/spp/download">www.hpe.com/servers/spp/download</a></p> <p><b>Note:</b> Both required driver and software updates are available from VUM online updates at: <a href="http://vibsdepot.hpe.com/hpe/preGen9/feb2017">http://vibsdepot.hpe.com/hpe/preGen9/feb2017</a></p>	<p><b>Software updates are required</b></p> <p>Image does not contain software versions specified in this Recipe</p> <p>Required software is available from: VUM online updates at: <a href="http://vibsdepot.hpe.com/hpe/preGen9/feb2017/index.xml">http://vibsdepot.hpe.com/hpe/preGen9/feb2017/index.xml</a></p> <p>Offline bundle updates at: <a href="http://vibsdepot.hpe.com/hpe/preGen9/feb2017/esxi-600-bundles">http://vibsdepot.hpe.com/hpe/preGen9/feb2017/esxi-600-bundles</a></p> <p><b>Note:</b> Both required driver and software updates are available from VUM online updates at: <a href="http://vibsdepot.hpe.com/hpe/preGen9/feb2017">http://vibsdepot.hpe.com/hpe/preGen9/feb2017</a></p>

VMware vSphere 6.7

VMware vSphere 6.7 U1

VMware vSphere 6.7 U2

No Pre-Gen9 Support

## VMware vSphere 6.5 U2

The HPE Custom Image for VMware vSphere 6.5 U2 (28 September 2018) that supports pre-Gen9 servers is available on vmware.com at:

<https://my.vmware.com/web/vmware/details?downloadGroup=OEM-ESXI65U2-HPE&productId=614>

HPE Custom Image	HPE Custom Image Identifier	vibsdepot directory	SPP	Comments
HPE Custom Image for VMware vSphere 6.5 U2 (28 September 2018) <sup>6</sup>	oem-build-650.U2.9.6.8	<a href="http://vibsdepot.hpe.com/hpe/preGen9/may2018">http://vibsdepot.hpe.com/hpe/preGen9/may2018</a>	<a href="#">Gen8.1 Post Production SPP</a> <sup>4</sup> + 6.5 U1 Supplement plus Hot Fix for the nhpsa driver <sup>5</sup>	Includes VMware patches <sup>6</sup>
HPE Custom Image for VMware vSphere 6.5 U2 (28 may 2018)	oem-build-650.U2.9.6.7	<a href="http://vibsdepot.hpe.com/hpe/preGen9/may2018">http://vibsdepot.hpe.com/hpe/preGen9/may2018</a>	<a href="#">Gen8.1 Post Production SPP</a> <sup>4</sup> + 6.5 U1 Supplement plus Hot Fix for the nhpsa driver <sup>5</sup>	Includes updated nhpsa driver <sup>5</sup>

<sup>4</sup> SPP does not contain any VMware vSphere online FW or SW components for VMware vSphere 6.5 U2. FW update for servers running VMware vSphere 6.5 U2 must be done via offline FW update. Software update for servers running VMware vSphere 6.5 U2 must be done using the HPE Custom Image or vibsdepot. Driver updates for servers running VMware vSphere 6.5 U2 can be done using the HPE Custom Image, vibsdepot or the VMware vSphere 6.5 U1 Supplement for the Gen8.1 Post Production SPP plus the Hot Fix for the nhpsa driver.

<sup>5</sup> This custom image includes an updated nhpsa driver. For details, refer to Customer Advisory [https://support.hpe.com/hpsc/doc/public/display?docId=emr\\_na-a00043167en\\_us&docLocale=en\\_US](https://support.hpe.com/hpsc/doc/public/display?docId=emr_na-a00043167en_us&docLocale=en_US)

<sup>6</sup> Same HPE added content as May 2018 image, but includes VMware vSphere Patch 6.5 U2b described in VMware KB at: <https://kb.vmware.com/s/article/55912> and the patch to fix the issue described in the VMware security advisory at: <https://www.vmware.com/security/advisories/VMSA-2018-0020.html>

## VMware vSphere 6.5 U1

The HPE Custom Image for VMware vSphere 6.5 U1 (30 Nov 2017) that supports pre-Gen9 servers is available on vmware.com at:  
<https://my.vmware.com/web/vmware/details?downloadGroup=OEM-ESXI65U1-HPE&productId=614>

HPE Custom Image	HPE Custom Image Identifier	vibsdepot directory	SPP	Comments
HPE Custom Image for VMware vSphere 6.5 U1 (30 November 2017)	hpe-build-650.U1.9.6.5.1	<a href="http://vibsdepot.hpe.com/hpe/preGen9/nov2017">http://vibsdepot.hpe.com/hpe/preGen9/nov2017</a>	<a href="#">Gen8.1 Post Production SPP</a> <sup>4</sup> + 6.5 U1 Supplement	

<sup>4</sup> SPP does not contain any VMware vSphere online FW or SW components for VMware vSphere 6.5 U1. FW update for servers running VMware vSphere 6.5 U1 must be done via offline FW update. Software update for servers running VMware vSphere 6.5 U1 must be done using the HPE Custom Image or vibsdepot. Driver updates for servers running VMware vSphere 6.5 U1 can be done using the HPE Custom Image, vibsdepot or the VMware vSphere 6.5 U1 Supplement for the Gen8.1 Post Production SPP.

## VMware vSphere 6.5

The HPE Custom Image for VMware vSphere 6.5 (08 May 2017) that supports pre-Gen9 servers is available on vmware.com at:

<https://my.vmware.com/web/vmware/details?downloadGroup=OEM-ESXI65B-HPE&productId=614>

HPE Custom Image	HPE Custom Image Identifier	vibsdepot directory	SPP	Comments
HPE Custom Image for VMware vSphere 6.5 (08 May 2017)	hpe-build-650.9.6.5.27	<a href="http://vibsdepot.hpe.com/hpe/preGen9/may2017">http://vibsdepot.hpe.com/hpe/preGen9/may2017</a>	<a href="#">Gen8.1 Post Production SPP</a> <sup>4</sup> <a href="#">2017.04.0</a> <sup>4</sup>	6.5 Respin including VMware P01 Last Pre-Gen9 support
NA	NA	<a href="http://vibsdepot.hpe.com/hpe/preGen9/jan2017">http://vibsdepot.hpe.com/hpe/preGen9/jan2017</a> <sup>3</sup>	NA	6.5 OS Release hpilo driver HotFix
HPE Custom Image for VMware vSphere 6.5 (18 November 2016)	hpe-build-650.9.6.0.28	<a href="http://vibsdepot.hpe.com/hpe/preGen9/nov2016">http://vibsdepot.hpe.com/hpe/preGen9/nov2016</a>	<a href="#">2016.10.0</a> <sup>4</sup>	6.5 GA OS Release

<sup>3</sup> vibsdepot directory only contains 6.5 HPE value add software components with the hpilo driver HotFix. Should be used with previous 6.5 release.

<sup>4</sup> SPP does not contain any VMware vSphere online FW or SW components for VMware vSphere 6.5. FW update for servers running VMware vSphere 6.5 must be done via offline FW update. Software and driver update for servers running VMware vSphere 6.5 must be done using the HPE Custom Image or vibsdepot.

## VMware vSphere 6.0 U3

The HPE Custom Image for VMware vSphere 6.0 Update 3 (28 September 2018) that supports Pre-Gen9 servers is available on vmware.com on the bottom of the page at: <https://my.vmware.com/web/vmware/details?downloadGroup=OEM-ESXI60U3-HPE&productId=491>

### Gen8 servers

HPE Custom Image	HPE Custom Image Identifier	vibsdepot directory	SPP	Comments
HPE Custom Image for VMware vSphere 6.0 U3 (28 September 2018) <sup>9</sup>	oem-build-600.9.8.5	<a href="http://vibsdepot.hpe.com/hpe/preGen9/feb2017">http://vibsdepot.hpe.com/hpe/preGen9/feb2017</a>	<a href="#">Gen8.1 Post Production SPP 2017.04.0</a> <sup>4</sup> <a href="#">2016.10.0</a> <sup>4</sup>	Includes VMware patches <sup>9</sup>
HPE Custom Image for VMware vSphere 6.0 U3 (12 June 2018)	oem-build-600.9.8.0-2494585	<a href="http://vibsdepot.hpe.com/hpe/preGen9/feb2017">http://vibsdepot.hpe.com/hpe/preGen9/feb2017</a>	<a href="#">Gen8.1 Post Production SPP 2017.04.0</a> <sup>4</sup> <a href="#">2016.10.0</a> <sup>4</sup>	Gen8 6.0U3 OS Release <sup>8</sup>
HPE Custom Image for VMware vSphere 6.0 U3 (23 February 2017)	hpe-build-600.9.7.0.17-2494585	<a href="http://vibsdepot.hpe.com/hpe/preGen9/feb2017">http://vibsdepot.hpe.com/hpe/preGen9/feb2017</a>	<a href="#">Gen8.1 Post Production SPP 2017.04.0</a> <sup>4</sup> <a href="#">2016.10.0</a> <sup>4</sup>	Gen8 6.0U3 OS Release Last Pre-Gen9 support

<sup>4</sup> SPP does not contain any VMware vSphere online FW or SW components for VMware vSphere 6.0 U3. FW update for servers running VMware vSphere 6.0 U3 must be done via offline FW update. Software and driver update for servers running VMware vSphere 6.0 U3 must be done using the HPE Custom Image or vibsdepot.

<sup>8</sup> Same HPE added content as Feb 2017 image, but includes the vSphere 6.0 U3e update. For more information, see the VMware Knowledge Base Article at: <https://kb.vmware.com/s/article/52451>

<sup>9</sup> Same HPE added content as Feb 2017 image, but includes vSphere 6.0 U3 Patch 07 described in VMware KB at: <https://kb.vmware.com/s/article/53627> and the patch to fix the issue described in the VMware security advisory at: <https://www.vmware.com/security/advisories/VMSA-2018-0020.html>



## G7 and earlier servers

HPE Custom Image	HPE Custom Image Identifier	vibsdepot directory	SPP	Comments
HPE Custom Image for VMware vSphere 6.0 U3 (28 September 2018)	oem-build-600.9.8.5	<a href="http://vibsdepot.hpe.com/hpe/preGen9/feb2017">http://vibsdepot.hpe.com/hpe/preGen9/feb2017</a>	<a href="#">Gen8.1 Post Production SPP 2017.04.0</a> <sup>4</sup> <a href="#">2016.10.0</a> <sup>4</sup>	Gen8 6.0U3 OS Release <sup>9</sup>
HPE Custom Image for VMware vSphere 6.0 U3 (12 June 2018)	oem-build-600.9.8.0-2494585	<a href="http://vibsdepot.hpe.com/hpe/preGen9/feb2017">http://vibsdepot.hpe.com/hpe/preGen9/feb2017</a>	<a href="#">Gen8.1 Post Production SPP 2017.04.0</a> <sup>4</sup> <a href="#">2016.10.0</a> <sup>4</sup>	Gen8 6.0U3 OS Release <sup>8</sup>
HPE Custom Image for VMware vSphere 6.0 U3 (23 February 2017)	hpe-build-600.9.7.0.17-2494585	<a href="http://vibsdepot.hpe.com/hpe/preGen9/feb2017">http://vibsdepot.hpe.com/hpe/preGen9/feb2017</a>	<a href="#">2017.04.0</a> <sup>4</sup> <a href="#">2016.10.0</a> <sup>4</sup>	G7 and earlier 6.0U3 OS Release Last Pre-Gen9 support

<sup>4</sup> SPP does not contain any VMware vSphere online FW or SW components for VMware vSphere 6.0 U3. FW update for servers running VMware vSphere 6.0 U3 must be done via offline FW update. Software and driver update for servers running VMware vSphere 6.0 U3 must be done using the HPE Custom Image or vibsdepot.

<sup>8</sup> Same HPE added content as Feb 2017 image, but includes the vSphere 6.0 U3e update. For more information, see the VMware Knowledge Base Article at: <https://kb.vmware.com/s/article/52451>

<sup>9</sup> Same HPE added content as Feb 2017 image, but includes VMware vSphere 6.0 U3 Patch 07 described in VMware KB at: <https://kb.vmware.com/s/article/53627> and the patch to fix the issue described in the VMware security advisory at: <https://www.vmware.com/security/advisories/VMSA-2018-0020.html>

## VMware vSphere 6.0 U2

No Gen10 or newer support.

HPE Custom Image	HPE Custom Image Identifier	vibsdepot directory	SPP	Comments
HPE Custom Image for VMware vSphere 6.0 U2 (09 December 2016)	hpe-build-600.9.6.5.7-2494585	<a href="http://vibsdepot.hpe.com/hpe/preGen9/dec2016">http://vibsdepot.hpe.com/hpe/preGen9/dec2016</a>	<a href="#">2016.10.0</a>	Server/option updates
HP Custom Image for VMware vSphere 6.0 U2 (24 October 2016)	hpe-build-600.9.6.0.49-2494585	<a href="http://vibsdepot.hpe.com/hpe/preGen9/oct2016">http://vibsdepot.hpe.com/hpe/preGen9/oct2016</a>	<a href="#">2016.10.0</a>	Server/option updates
HP Custom Image for VMware vSphere 6.0 U2 (01 April 2016)	hpe-build-600.9.5.0.48-2494585	<a href="http://vibsdepot.hpe.com/hpe/preGen9/apr2016">http://vibsdepot.hpe.com/hpe/preGen9/apr2016</a>	<a href="#">2016.04.0</a>	Server/option updates
HP Custom Image for VMware vSphere 6.0 U2 (15 March 2016)	hpe-build-600.U2.9.4.7.13-2494585	<a href="http://vibsdepot.hpe.com/hpe/preGen9/mar2016">http://vibsdepot.hpe.com/hpe/preGen9/mar2016</a>	<a href="#">2015.10.0</a>	6.0U2 OS Release

## VMware vSphere 6.0 U1

No Gen10 or newer support.

HPE Custom Image	HPE Custom Image Identifier	vibsdepot directory	SPP	Comments
HPE Custom Image for VMware vSphere 6.0 U1 (08 January 2016)	hpe-build-600.9.4.5.11-2494585	<a href="http://vibsdepot.hpe.com/hpe/preGen9/jan2016">http://vibsdepot.hpe.com/hpe/preGen9/jan2016</a>	<a href="#">2015.10.0</a>	6.0U1b with Skylake Support

## VMware vSphere 5.5 U3

No Gen10 or newer support.

HPE Custom Image	HPE Custom Image Identifier	vibsdepot directory	SPP	Comments
NA	NA	<a href="http://vibsdepot.hpe.com/hpe/preGen9/apr2017">http://vibsdepot.hpe.com/hpe/preGen9/apr2017</a> <sup>1</sup>	NA	5.5 HPE Utility Bundle Fix
HPE Custom Image for VMware vSphere 5.5 U3 (09 December 2016)	hp-build 550.9.6.5.9 - 1198610	<a href="http://vibsdepot.hpe.com/hpe/preGen9/dec2016">http://vibsdepot.hpe.com/hpe/preGen9/dec2016</a>	<a href="#">2017.04.0 G7 Post Production SPP</a>	Server/options updates
HP Custom Image for VMware vSphere 5.5 U3 (24 October 2016)	hp-build 550.9.6.0.45 - 1198610	<a href="http://vibsdepot.hpe.com/hpe/preGen9/oct2016">http://vibsdepot.hpe.com/hpe/preGen9/oct2016</a>	<a href="#">2016.10.0</a>	Server/option updates
HP Custom Image for VMware vSphere 5.5 U3 (01 April 2016)	hp-build 550.9.5.0.33 - 1198610	<a href="http://vibsdepot.hpe.com/hpe/preGen9/apr2016">http://vibsdepot.hpe.com/hpe/preGen9/apr2016</a>	<a href="#">2016.04.0</a>	Server/option updates
HP Custom Image for VMware vSphere 5.5 U3 (08 December 2015)	hp-build 550.9.4.5.7 - 1198610	<a href="http://vibsdepot.hpe.com/hpe/preGen9/dec2015">http://vibsdepot.hpe.com/hpe/preGen9/dec2015</a>	<a href="#">2015.10.0</a>	5.5U3b with Skylake Support

<sup>1</sup> vibsdepot directory only contains 5.5 HPE value add software components with the utility bundle fix. Should be used with previous 5.5 release.

2019.03.1 SPP

2019.03.0 SPP

2018.11.0 MSB

2018.09.0 MSB

2018.06.0 SPP

2018.03.0 SPP

2017.10.1 SPP

2017.07.2 SPP

No pre-Gen9 support

## Gen8.1 Post Production

Pre-Gen9 servers are only supported in the Post Production SPP.

VMware vSphere 6.5 U1 Supplement for the Gen8.1 Post Production SPP supports driver update for 6.5 U1 and 6.5 U2.

G7 servers are not supported with 6.5 or updates or with the Gen8.1 Post Production SPP.

Gen8.1 Post Production SPP does not contain any VMware vSphere online FW or SW components for VMware vSphere 6.5, 6.5 U1 or 6.5 U2, but the supplement for VMware vSphere 6.5 U1 does contain online driver components.

- FW update for servers running VMware vSphere 6.5, 6.5 U1 and 6.5 U2 must be done via offline FW update.
- Software and driver updates for servers running VMware vSphere 6.5 must be done using the HPE Custom Image or vibsdepot.
- Software updates for servers running VMware vSphere 6.5 U1 and 6.5 U2 must be done using the HPE Custom Image or vibsdepot.
- Driver updates for servers running VMware vSphere 6.5 U1 and 6.5 U2 can be done using the HPE Custom Image, vibsdepot or the VMware vSphere 6.5 U1 Supplement for the Gen8.1 Post Production SPP.

SPP documentation and downloads for the Gen8.1 SPP release can be found at <http://www.hpe.com/servers/spp/download?version=Gen8.1>

vSphere version	Firmware	Drivers	Software
6.5 U2	Gen8.1 Post Production SPP Offline FW update	<ul style="list-style-type: none"> <li>• HPE Custom Image for VMware vSphere 6.5 U2 (28 Sep. 2018)</li> <li>• vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/may2018">http://vibsdepot.hpe.com/hpe/preGen9/may2018</a></li> <li>• VMware vSphere 6.5 U1 Supplement for the Gen8.1 Post Production SPP Online Update plus Hot Fix for nhpsa driver</li> </ul>	<ul style="list-style-type: none"> <li>• HPE Custom Image for VMware vSphere 6.5 U2 (28 Sep. 2018)</li> <li>• vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/may2018">http://vibsdepot.hpe.com/hpe/preGen9/may2018</a></li> </ul>
6.5 U2	Gen8.1 Post Production SPP Offline FW update	<ul style="list-style-type: none"> <li>• HPE Custom Image for VMware vSphere 6.5 U2 (28 May 2018)</li> <li>• vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/may2018">http://vibsdepot.hpe.com/hpe/preGen9/may2018</a></li> <li>• VMware vSphere 6.5 U1 Supplement for the Gen8.1 Post Production SPP Online Update plus Hot Fix for nhpsa driver</li> </ul>	<ul style="list-style-type: none"> <li>• HPE Custom Image for VMware vSphere 6.5 U2 (28 May 2018)</li> <li>• vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/may2018">http://vibsdepot.hpe.com/hpe/preGen9/may2018</a></li> </ul>
6.5 U1	Gen8.1 Post Production SPP Offline FW update	<ul style="list-style-type: none"> <li>• HPE Custom Image for VMware vSphere 6.5 U1 (30 Nov. 2017)</li> <li>• vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/nov2017">http://vibsdepot.hpe.com/hpe/preGen9/nov2017</a></li> <li>• VMware vSphere 6.5 U1 Supplement for the Gen8.1 Post Production SPP Online Update</li> </ul>	<ul style="list-style-type: none"> <li>• HPE Custom Image for VMware vSphere 6.5 U1 (30 Nov. 2017)</li> <li>• vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/nov2017">http://vibsdepot.hpe.com/hpe/preGen9/nov2017</a></li> </ul>
6.5	Gen8.1 Post Production SPP Offline FW update	<ul style="list-style-type: none"> <li>• HPE Custom Image for VMware vSphere 6.5 (08 May 2017)</li> <li>• vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/may2017">http://vibsdepot.hpe.com/hpe/preGen9/may2017</a></li> </ul>	<ul style="list-style-type: none"> <li>• HPE Custom Image for VMware vSphere 6.5 (08 May 2017)</li> <li>• vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/may2017">http://vibsdepot.hpe.com/hpe/preGen9/may2017</a></li> </ul>

vSphere version	Firmware	Drivers	Software
6.0 U3	Gen8.1 Post Production SPP Online or Offline FW update	<ul style="list-style-type: none"> <li>• HPE Custom Image for VMware vSphere 6.0 U3 (28 Sep. 2018)</li> <li>• vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/feb2017">http://vibsdepot.hpe.com/hpe/preGen9/feb2017</a></li> <li>• G8.1 Post Production SPP Online Update</li> </ul>	<ul style="list-style-type: none"> <li>• HPE Custom Image for VMware vSphere 6.0 U3 (28 Sep. 2018)</li> <li>• vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/feb2017">http://vibsdepot.hpe.com/hpe/preGen9/feb2017</a></li> </ul>
6.0 U3	Gen8.1 Post Production SPP Online or Offline FW update	<ul style="list-style-type: none"> <li>• HPE Custom Image for VMware vSphere 6.0 U3 (12 June 2018)</li> <li>• vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/feb2017">http://vibsdepot.hpe.com/hpe/preGen9/feb2017</a></li> <li>• G8.1 Post Production SPP Online Update</li> </ul>	<ul style="list-style-type: none"> <li>• HPE Custom Image for VMware vSphere 6.0 U3 (12 June 2018)</li> <li>• vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/feb2017">http://vibsdepot.hpe.com/hpe/preGen9/feb2017</a></li> </ul>
6.0 U3	Gen8.1 Post Production SPP Online or Offline FW update	<ul style="list-style-type: none"> <li>• HPE Custom Image for VMware vSphere 6.0 U3 (23 Feb. 2017)</li> <li>• vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/feb2017">http://vibsdepot.hpe.com/hpe/preGen9/feb2017</a></li> <li>• Gen8.1 Post Production SPP Online Update</li> </ul>	<ul style="list-style-type: none"> <li>• HPE Custom Image for VMware vSphere 6.0 U3 (23 Feb. 2017)</li> <li>• vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/feb2017">http://vibsdepot.hpe.com/hpe/preGen9/feb2017</a></li> </ul>

## G7.1 Post Production

First G7 Post Production SPP.

Pre-Gen9 servers are only supported in the Post Production SPP.

G7 servers are not supported on VMware vSphere 6.5 and updates.

G7 Post Production SPP does not support VMware vSphere 6.5 U1 or 6.5

SPP documentation and downloads for the G7.1 Post Production SPP release can be found at <http://www.hpe.com/servers/spp/download?version=G7.1>

vSphere version	Firmware	Drivers	Software
6.0 U3	G7.1 Post Production SPP Online or Offline FW update	<ul style="list-style-type: none"> <li>HPE Custom Image for VMware vSphere 6.0 U3 (28 September 2018)</li> <li>vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/feb2017">http://vibsdepot.hpe.com/hpe/preGen9/feb2017</a></li> <li>G7.1 Post Production SPP Online Update</li> </ul>	<ul style="list-style-type: none"> <li>HPE Custom Image for VMware vSphere 6.0 U3 (28 September 2018)</li> <li>vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/feb2017">http://vibsdepot.hpe.com/hpe/preGen9/feb2017</a></li> </ul>
6.0 U3	G7.1 Post Production SPP Online or Offline FW update	<ul style="list-style-type: none"> <li>HPE Custom Image for VMware vSphere 6.0 U3 (12 June 2018)</li> <li>vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/feb2017">http://vibsdepot.hpe.com/hpe/preGen9/feb2017</a></li> <li>G7.1 Post Production SPP Online Update</li> </ul>	<ul style="list-style-type: none"> <li>HPE Custom Image for VMware vSphere 6.0 U3 (12 June 2018)</li> <li>vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/feb2017">http://vibsdepot.hpe.com/hpe/preGen9/feb2017</a></li> </ul>
5.5 U3	G7.1 Post Production SPP Online or Offline FW update	<ul style="list-style-type: none"> <li>HPE Custom Image for VMware vSphere 5.5 U3 (09 December 2016) + <a href="http://vibsdepot.hpe.com/hpe/preGen9/apr2017">http://vibsdepot.hpe.com/hpe/preGen9/apr2017</a></li> <li>vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/dec2016">http://vibsdepot.hpe.com/hpe/preGen9/dec2016</a> + <a href="http://vibsdepot.hpe.com/hpe/preGen9/apr2017">http://vibsdepot.hpe.com/hpe/preGen9/apr2017</a></li> <li>G7.1 Post Production SPP online update</li> </ul>	<ul style="list-style-type: none"> <li>HPE Custom Image for VMware vSphere 5.5 U3 (09 December 2016) + <a href="http://vibsdepot.hpe.com/hpe/preGen9/apr2017">http://vibsdepot.hpe.com/hpe/preGen9/apr2017</a></li> <li>vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/dec2016">http://vibsdepot.hpe.com/hpe/preGen9/dec2016</a> + <a href="http://vibsdepot.hpe.com/hpe/preGen9/apr2017">http://vibsdepot.hpe.com/hpe/preGen9/apr2017</a></li> </ul>



## 2017.04.0 SPP

2017.04.0 SPP does not contain any VMware vSphere online FW or SW components for VMware vSphere 6.0 U3, 6.5 or 6.5 U1. FW update for servers running VMware vSphere 6.0 U3, 6.5 and 6.5 U1 must be done via offline FW update. Software and driver update for servers running VMware vSphere 6.0 U3, 6.5 and 6.5 U1 must be done using the HPE Custom Image or vibsdepot.

Last SPP to support 5.5 U3.

Last full SPP to support Pre-Gen9 servers.

SPP documentation and downloads for the 2017.04.0 SPP release can be found at <http://www.hpe.com/servers/spp/download?version=2017.04.0>

vSphere version	Firmware	Drivers	Software
6.5 U1	2017.04.0 SPP Offline FW update	<ul style="list-style-type: none"> <li>HPE Custom Image for VMware vSphere 6.5 U1 (30 Nov 2017)</li> <li>vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/may2017">http://vibsdepot.hpe.com/hpe/preGen9/may2017</a></li> </ul>	<ul style="list-style-type: none"> <li>HPE Custom Image for VMware vSphere 6.5 U1 (30 Nov 2017)</li> <li>vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/may2017">http://vibsdepot.hpe.com/hpe/preGen9/may2017</a></li> </ul>
6.5	2017.04.0 SPP Offline FW update	<ul style="list-style-type: none"> <li>HPE Custom Image for VMware vSphere 6.5 (08 May 2017)</li> <li>vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/may2017">http://vibsdepot.hpe.com/hpe/preGen9/may2017</a></li> </ul>	<ul style="list-style-type: none"> <li>HPE Custom Image for VMware vSphere 6.5 (08 May 2017)</li> <li>vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/may2017">http://vibsdepot.hpe.com/hpe/preGen9/may2017</a></li> </ul>
6.0 U3	2017.04.0 SPP Offline FW update	<ul style="list-style-type: none"> <li>HPE Custom Image for VMware vSphere 6.0 U3 (23 February 2017)</li> <li>vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/feb2017">http://vibsdepot.hpe.com/hpe/preGen9/feb2017</a></li> </ul>	<ul style="list-style-type: none"> <li>HPE Custom Image for VMware vSphere 6.0 U3 (23 February 2017)</li> <li>vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/feb2017">http://vibsdepot.hpe.com/hpe/preGen9/feb2017</a></li> </ul>
5.5 U3	2017.04.0 SPP Online or Offline FW update	<ul style="list-style-type: none"> <li>HPE Custom Image for VMware vSphere 5.5 U3 (09 December 2016) + <a href="http://vibsdepot.hpe.com/hpe/preGen9/apr2017">http://vibsdepot.hpe.com/hpe/preGen9/apr2017</a></li> <li>vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/dec2016">http://vibsdepot.hpe.com/hpe/preGen9/dec2016</a> + <a href="http://vibsdepot.hpe.com/hpe/preGen9/apr2017">http://vibsdepot.hpe.com/hpe/preGen9/apr2017</a></li> <li>2017.04.0 SPP Online update</li> </ul>	<ul style="list-style-type: none"> <li>HPE Custom Image for VMware vSphere 5.5 U3 (09 December 2016) + <a href="http://vibsdepot.hpe.com/hpe/preGen9/apr2017">http://vibsdepot.hpe.com/hpe/preGen9/apr2017</a></li> <li>vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/dec2016">http://vibsdepot.hpe.com/hpe/preGen9/dec2016</a> + <a href="http://vibsdepot.hpe.com/hpe/preGen9/apr2017">http://vibsdepot.hpe.com/hpe/preGen9/apr2017</a></li> </ul>

## 2016.10.0 SPP

2016.10.0 SPP does not contain any VMware vSphere online FW or SW components for VMware vSphere 6.0 U3 or 6.5. FW update for servers running VMware vSphere 6.0 U3 and 6.5 must be done via offline FW update. Software and driver update for servers running VMware vSphere 6.0 U3 and 6.5 must be done using the HPE Custom Image or vibsdepot.

First SPP to support 6.5 and 6.0 U3. Last SPP to support 6.0 U2. SPP documentation and downloads for the 2016.10.0 SPP release can be found at [https://support.hpe.com/hpsc/swd/public/detail?swItemId=MTX\\_3c2bfc8c3b446a7a9451c4ab9](https://support.hpe.com/hpsc/swd/public/detail?swItemId=MTX_3c2bfc8c3b446a7a9451c4ab9)

vSphere version	Firmware	Drivers	Software
6.5	2016.10.0 SPP Offline FW update	<ul style="list-style-type: none"> <li>HPE Custom Image for VMware vSphere 6.5 (18 November 2016) + <a href="http://vibsdepot.hpe.com/hpe/preGen9/jan2017">http://vibsdepot.hpe.com/hpe/preGen9/jan2017</a></li> <li>vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/nov2016">http://vibsdepot.hpe.com/hpe/preGen9/nov2016</a> + <a href="http://vibsdepot.hpe.com/hpe/preGen9/jan2017">http://vibsdepot.hpe.com/hpe/preGen9/jan2017</a></li> </ul>	<ul style="list-style-type: none"> <li>HPE Custom Image for VMware vSphere 6.5 (18 November 2016) + <a href="http://vibsdepot.hpe.com/hpe/preGen9/jan2017">http://vibsdepot.hpe.com/hpe/preGen9/jan2017</a></li> <li>vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/nov2016">http://vibsdepot.hpe.com/hpe/preGen9/nov2016</a> + <a href="http://vibsdepot.hpe.com/hpe/preGen9/jan2017">http://vibsdepot.hpe.com/hpe/preGen9/jan2017</a></li> </ul>
6.0 U3	2016.10.0 SPP Offline FW update	<ul style="list-style-type: none"> <li>HPE Custom Image for VMware vSphere 6.0 U3 (23 February 2017)</li> <li>vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/feb2017">http://vibsdepot.hpe.com/hpe/preGen9/feb2017</a></li> </ul>	<ul style="list-style-type: none"> <li>HPE Custom Image for VMware vSphere 6.0 U3 (23 February 2017)</li> <li>vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/feb2017">http://vibsdepot.hpe.com/hpe/preGen9/feb2017</a></li> </ul>
6.0 U2	2016.10.0 SPP Online or Offline FW update	<ul style="list-style-type: none"> <li>HPE Custom Image for VMware vSphere 6.0 U2 (09 December 2016)</li> <li>vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/dec2016">http://vibsdepot.hpe.com/hpe/preGen9/dec2016</a></li> <li>2016.10.0 SPP Online update</li> </ul>	<ul style="list-style-type: none"> <li>HPE Custom Image for VMware vSphere 6.0 U2 (09 December 2016)</li> <li>vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/dec2016">http://vibsdepot.hpe.com/hpe/preGen9/dec2016</a></li> </ul>
6.0 U2	2016.10.0 SPP Online or Offline FW update	<ul style="list-style-type: none"> <li>HP Custom Image for VMware vSphere 6.0 U2 (24 October 2016)</li> <li>vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/oct2016">http://vibsdepot.hpe.com/hpe/preGen9/oct2016</a></li> <li>2016.10.0 SPP Online update</li> </ul>	<ul style="list-style-type: none"> <li>HP Custom Image for VMware vSphere 6.0 U2 (24 October 2016)</li> <li>vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/oct2016">http://vibsdepot.hpe.com/hpe/preGen9/oct2016</a></li> </ul>
5.5 U3	2016.10.0 SPP Online or Offline FW update	<ul style="list-style-type: none"> <li>HPE Custom Image for VMware vSphere 5.5 U3 (09 December 2016)</li> <li>vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/dec2016">http://vibsdepot.hpe.com/hpe/preGen9/dec2016</a></li> <li>2016.10.0 SPP Online update</li> </ul>	<ul style="list-style-type: none"> <li>HPE Custom Image for VMware vSphere 5.5 U3 (09 December 2016)</li> <li>vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/dec2016">http://vibsdepot.hpe.com/hpe/preGen9/dec2016</a></li> </ul>
5.5 U3	2016.10.0 SPP Online or Offline FW update	<ul style="list-style-type: none"> <li>HP Custom Image for VMware vSphere 5.5 U3 (24 October 2016)</li> <li>vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/oct2016">http://vibsdepot.hpe.com/hpe/preGen9/oct2016</a></li> <li>2016.10.0 SPP Online update</li> </ul>	<ul style="list-style-type: none"> <li>HPE Custom Image for VMware vSphere 5.5 U3 (24 October 2016)</li> <li>vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/oct2016">http://vibsdepot.hpe.com/hpe/preGen9/oct2016</a></li> </ul>

## 2016.04.0 SPP

Last SPP to support 5.1 U3

SPP documentation and downloads for the 2016.04.0 SPP release can be found at

[https://support.hpe.com/hpsc/swd/public/detail?swItemId=MTX\\_d32057eee2bc45f187b3c3fbcf](https://support.hpe.com/hpsc/swd/public/detail?swItemId=MTX_d32057eee2bc45f187b3c3fbcf)

vSphere version	Firmware	Drivers	Software
6.0 U2	2016.04.0 SPP Online or Offline FW update	<ul style="list-style-type: none"> <li>• HP Custom Image for VMware vSphere 6.0 U2 (01 April 2016)</li> <li>• vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/apr2016">http://vibsdepot.hpe.com/hpe/preGen9/apr2016</a></li> <li>• 2016.04.0 SPP Online update</li> </ul>	<ul style="list-style-type: none"> <li>• HP Custom Image for VMware vSphere 6.0 U2 (01 April 2016)</li> <li>• vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/apr2016">http://vibsdepot.hpe.com/hpe/preGen9/apr2016</a></li> </ul>
5.5 U3	2016.04.0 SPP Online or Offline FW update	<ul style="list-style-type: none"> <li>• HP Custom Image for VMware vSphere 5.5 U3 (01 April 2016)</li> <li>• vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/apr2016">http://vibsdepot.hpe.com/hpe/preGen9/apr2016</a></li> <li>• 2016.04.0 SPP Online update</li> </ul>	<ul style="list-style-type: none"> <li>• HP Custom Image for VMware vSphere 5.5 U3 (01 April 2016)</li> <li>• vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/apr2016">http://vibsdepot.hpe.com/hpe/preGen9/apr2016</a></li> </ul>
5.1 U3	2016.04.0 SPP Online or Offline FW update	<ul style="list-style-type: none"> <li>• HP Custom Image for VMware ESXi 5.1.0 U3 (01 April 2016)</li> <li>• vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/apr2016">http://vibsdepot.hpe.com/hpe/preGen9/apr2016</a></li> <li>• 2016.04.0 SPP Online update</li> </ul>	<ul style="list-style-type: none"> <li>• HP Custom Image for VMware ESXi 5.1.0 U3 (01 April 2016)</li> <li>• vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/apr2016">http://vibsdepot.hpe.com/hpe/preGen9/apr2016</a></li> </ul>

## 2015.10.0 SPP

SPP documentation and downloads for the 2016.04.0 SPP release can be found at [https://support.hpe.com/hpsc/swd/public/detail?swItemId=MTX\\_1d06af9e8a0a4e43b8981b4471](https://support.hpe.com/hpsc/swd/public/detail?swItemId=MTX_1d06af9e8a0a4e43b8981b4471)

vSphere version	Firmware	Drivers	Software
6.0 U2	2015.10.0 SPP Online or Offline FW update	<ul style="list-style-type: none"> <li>HP Custom Image for VMware vSphere 6.0 U2 (15 March 2016)</li> <li>vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/mar2016">http://vibsdepot.hpe.com/hpe/preGen9/mar2016</a></li> <li>2015.10.0 SPP Online update</li> </ul>	<ul style="list-style-type: none"> <li>HP Custom Image for VMware vSphere 6.0 U2 (15 March 2016)</li> <li>vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/mar2016">http://vibsdepot.hpe.com/hpe/preGen9/mar2016</a></li> </ul>
6.0 U1	2015.10.0 SPP Online or Offline FW update	<ul style="list-style-type: none"> <li>HPE Custom Image for VMware vSphere 6.0 U1 (08 January 2016)</li> <li>2015.10.0 SPP Online update</li> </ul>	<ul style="list-style-type: none"> <li>HPE Custom Image for VMware vSphere 6.0 U1 (08 January 2016)</li> </ul>
5.5 U3	2015.10.0 SPP Online or Offline FW update	<ul style="list-style-type: none"> <li>HP Custom Image for VMware vSphere 5.5 U3 (08 December 2015)</li> <li>vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/dec2015">http://vibsdepot.hpe.com/hpe/preGen9/dec2015</a></li> <li>2015.10.0 SPP Online update</li> </ul>	<ul style="list-style-type: none"> <li>HP Custom Image for VMware vSphere 5.5 U3 (08 December 2015)</li> <li>vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/dec2015">http://vibsdepot.hpe.com/hpe/preGen9/dec2015</a></li> </ul>
5.1 U3	2015.10.0 SPP Online or Offline FW update	<ul style="list-style-type: none"> <li>HP Custom Image for VMware ESXi 5.1.0 U3 (09 November 2015)</li> <li>vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/nov2015">http://vibsdepot.hpe.com/hpe/preGen9/nov2015</a></li> <li>2015.10.0 SPP Online update</li> </ul>	<ul style="list-style-type: none"> <li>HP Custom Image for VMware ESXi 5.1.0 U3 (09 November 2015)</li> <li>vibsdepot at <a href="http://vibsdepot.hpe.com/hpe/preGen9/nov2015">http://vibsdepot.hpe.com/hpe/preGen9/nov2015</a></li> </ul>

## Revision History

Date	Version	Change Description
06.05.2019	1.14.1	Removed reference to Synergy links
04.26.2019	1.14	Added 2019.03.1 SPP
04.11.2019	1.13	Added VMware vSphere 6.7 U2
04.01.2019	1.12	Added 2019.03.0 SPP
01.24.2019	1.11.3	Added note 2018.03.0 SPP and newer now includes HPE value-add software.
12.03.2018	1.11.2	Added reference to Synergy and Superdome links.
11.28.2018	1.11.1	Clarified how to update previously released HPE Custom Images to newer SPPs
11.27.2018	1.11	Added 2018.11.0 MSB.
10.04.2018	1.10	Added VMware vSphere 6.7 U1
09.28.2018	1.9	Added 2018.09.0 MSB and September 2018 Pre-Gen9 HPE Custom Images for 6.0 U3 and 6.5 U2.

07.23.2018	1.8.1	Fixed Gen8.1 SPP references for 6.5 U2 to include 6.5 U1 supplement and nhpsa hot fix. Clarifications and change HPE SPP to SPP.
06.26.2018	1.8	Added new 6.0 U3 HPE Custom Image and included in Gen8.1 and G7.1 Post Production SPP tables.
06.12.2018	1.7	Added 2018.06.0 SPP
05.28.2018	1.6	Update version and date for 6.5 U2 release
05.03.2018	1.5	Added VMware vSphere 6.5 U2 release Update vibsdepot URLs to new preGen9 URLs
04.17.2018	1.4	Added VMware vSphere 6.7 Added links to SPP downloads and documentation Remove Gen8.0 Post Production SPP, replace by Gen8.1
02.05.2018	1.3	Added 2017.10.1 and 2018.03.0 SPP as no support for pre-Gen9 servers.
11.30.2017	1.2	Added VMware vSphere 6.5 U1 Supplement for Gen8.1 Post Production SPP Fix 5.5 U3 table to list 2017.04.0 SPP as supported with December HPE Custom Image Correct G7 Post Production SPP table and add the G7 Post Production SPP to the 5.5 U3 table
10.26.2017	1.1	Added all Post Production SPP releases
10.06.2017	1.0	Initial version Current HPE driver, support, and security alerts delivered directly to your desktop
<p><b>Get connected</b>  <a href="http://hpe.com/info/getconnected">hpe.com/info/getconnected</a></p>		

© Copyright 2015 Hewlett Packard Enterprise Development Company, L.P. The information contained herein is subject to change without notice. The only warranties for HPE products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. HPE shall not be liable for technical or editorial errors or omissions contained herein.

Trademark acknowledgments, if needed.